










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
<b>COMPRESSORS</b>					
<b>COM-CAQ</b>	 <b>CAPACITORS &amp; START DEVICES</b>				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$48.10	\$64.10	\$40.88	\$7.21
<b>COM-CHQ</b>					
<b>COM-CHQ</b>	 <b>HERMETIC COMPOSITE * MECH FAILURE</b>				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,153.74	\$1,283.64	\$980.68	\$173.06
<b>CONDENSATE</b>					
<b>COD-COP</b>	 <b>CONDENSATE PUMPS</b>				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$128.74	\$140.44	\$109.43	\$19.31
<b>CONTROLS</b>					
<b>CON-COU</b>	 <b>CONTACTORS * 2 POLE</b>				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$58.35	\$74.35	\$49.59	\$8.75
<b>GAS HEATING</b>					
<b>GAS-IGO</b>	 <b>IGNITORS</b>				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$84.67	\$105.17	\$71.97	\$12.70
<b>GAS-THR</b>	 <b>THERMOCOUPLES</b>				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$51.86	\$69.36	\$44.08	\$7.78
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$19.86	\$21.36	\$16.88	\$2.98
<b>MOTORS</b>					
<b>MOT-CFN</b>	 <b>COND FAN MOTORS * SLEEVE BEARINGS</b>				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$197.04	\$229.14	\$167.48	\$29.56
<b>MOT-MOD</b>	 <b>DIRECT DRIVE MOTORS</b>				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$294.61	\$340.51	\$250.42	\$44.19
<b>REFRIGERANTS</b>					
<b>REF-RRR</b>	 <b>REFRIGERANTS</b>				
017660-0011	R22 PER LB (1st LB)	\$24.80	\$30.20	\$21.08	\$3.72
017661-0000	R22 PER LB (ADDL LBS)	\$14.00	\$14.00	\$11.90	\$2.10