










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
COMPRESSORS					
COM-CAQ	 CAPACITORS & START DEVICES				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$58.76	\$80.10	\$49.95	\$8.81
COM-CHQ					
COM-CHQ	 HERMETIC COMPOSITE * MECH FAILURE				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,240.34	\$1,413.54	\$1,054.29	\$186.05
CONDENSATE					
COD-COP	 CONDENSATE PUMPS				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$136.54	\$152.14	\$116.06	\$20.48
CONTROLS					
CON-COU	 CONTACTORS * 2 POLE				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$69.01	\$90.35	\$58.66	\$10.35
GAS HEATING					
GAS-IGO	 IGNITORS				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$98.33	\$125.67	\$83.58	\$14.75
GAS-THR	 THERMOCOUPLES				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$63.53	\$86.86	\$54.00	\$9.53
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$20.86	\$22.86	\$17.73	\$3.13
MOTORS					
MOT-CFN	 COND FAN MOTORS * SLEEVE BEARINGS				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$218.44	\$261.24	\$185.67	\$32.77
MOT-MOD	 DIRECT DRIVE MOTORS				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$325.21	\$386.41	\$276.43	\$48.78
REFRIGERANTS					
REF-RRR	 REFRIGERANTS				
017660-0011	R22 PER LB (1st LB)	\$29.40	\$36.60	\$24.99	\$4.41
017661-0000	R22 PER LB (ADDL LBS)	\$15.00	\$15.00	\$12.75	\$2.25