










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
COMPRESSORS					
COM-CAQ	 CAPACITORS & START DEVICES				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$69.43	\$96.10	\$59.01	\$10.41
COM-CHQ					
COM-CHQ	 HERMETIC COMPOSITE * MECH FAILURE				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,326.94	\$1,543.44	\$1,127.90	\$199.04
CONDENSATE					
COD-COP	 CONDENSATE PUMPS				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$144.34	\$163.84	\$122.69	\$21.65
CONTROLS					
CON-COU	 CONTACTORS * 2 POLE				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$79.68	\$106.35	\$67.73	\$11.95
GAS HEATING					
GAS-IGO	 IGNITORS				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$112.00	\$146.17	\$95.20	\$16.80
GAS-THR	 THERMOCOUPLES				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$75.19	\$104.36	\$63.91	\$11.28
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$21.86	\$24.36	\$18.58	\$3.28
MOTORS					
MOT-CFN	 COND FAN MOTORS * SLEEVE BEARINGS				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$239.84	\$293.34	\$203.86	\$35.98
MOT-MOD	 DIRECT DRIVE MOTORS				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$355.81	\$432.31	\$302.44	\$53.37
REFRIGERANTS					
REF-RRR	 REFRIGERANTS				
017660-0011	R22 PER LB (1st LB)	\$35.00	\$44.00	\$29.75	\$5.25
017661-0000	R22 PER LB (ADDL LBS)	\$17.00	\$17.00	\$14.45	\$2.55