










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
<b>COMPRESSORS</b>					
<b>COM-CAQ</b>	 <b>CAPACITORS &amp; START DEVICES</b>				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$90.76	\$128.10	\$77.15	\$13.61
<b>COM-CHQ</b>					
<b>COM-CHQ</b>	 <b>HERMETIC COMPOSITE * MECH FAILURE</b>				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,500.14	\$1,803.24	\$1,275.12	\$225.02
<b>CONDENSATE</b>					
<b>COD-COP</b>	 <b>CONDENSATE PUMPS</b>				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$159.94	\$187.24	\$135.95	\$23.99
<b>CONTROLS</b>					
<b>CON-COU</b>	 <b>CONTACTORS * 2 POLE</b>				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$101.01	\$138.35	\$85.86	\$15.15
<b>GAS HEATING</b>					
<b>GAS-IGO</b>	 <b>IGNITORS</b>				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$139.33	\$187.17	\$118.43	\$20.90
<b>GAS-THR</b>	 <b>THERMOCOUPLES</b>				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$98.53	\$139.36	\$83.75	\$14.78
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$23.86	\$27.36	\$20.28	\$3.58
<b>MOTORS</b>					
<b>MOT-CFN</b>	 <b>COND FAN MOTORS * SLEEVE BEARINGS</b>				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$282.64	\$357.54	\$240.24	\$42.40
<b>MOT-MOD</b>	 <b>DIRECT DRIVE MOTORS</b>				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$417.01	\$524.11	\$354.46	\$62.55
<b>REFRIGERANTS</b>					
<b>REF-RRR</b>	 <b>REFRIGERANTS</b>				
017660-0011	R22 PER LB (1st LB)	\$43.20	\$55.80	\$36.72	\$6.48
017661-0000	R22 PER LB (ADDL LBS)	\$18.00	\$18.00	\$15.30	\$2.70