










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
<b>COMPRESSORS</b>					
<b>COM-CAQ</b>	 <b>CAPACITORS &amp; START DEVICES</b>				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$101.43	\$144.10	\$86.21	\$15.21
<b>COM-CHQ</b>					
<b>COM-CHQ</b>	 <b>HERMETIC COMPOSITE * MECH FAILURE</b>				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,586.74	\$1,933.14	\$1,348.73	\$238.01
<b>CONDENSATE</b>					
<b>COD-COP</b>	 <b>CONDENSATE PUMPS</b>				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$167.74	\$198.94	\$142.58	\$25.16
<b>CONTROLS</b>					
<b>CON-COU</b>	 <b>CONTACTORS * 2 POLE</b>				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$111.68	\$154.35	\$94.93	\$16.75
<b>GAS HEATING</b>					
<b>GAS-IGO</b>	 <b>IGNITORS</b>				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$153.00	\$207.67	\$130.05	\$22.95
<b>GAS-THR</b>	 <b>THERMOCOUPLES</b>				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$110.19	\$156.86	\$93.66	\$16.53
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$24.86	\$28.86	\$21.13	\$3.73
<b>MOTORS</b>					
<b>MOT-CFN</b>	 <b>COND FAN MOTORS * SLEEVE BEARINGS</b>				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$304.04	\$389.64	\$258.43	\$45.61
<b>MOT-MOD</b>	 <b>DIRECT DRIVE MOTORS</b>				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$447.61	\$570.01	\$380.47	\$67.14
<b>REFRIGERANTS</b>					
<b>REF-RRR</b>	 <b>REFRIGERANTS</b>				
017660-0011	R22 PER LB (1st LB)	\$48.80	\$63.20	\$41.48	\$7.32
017661-0000	R22 PER LB (ADDL LBS)	\$20.00	\$20.00	\$17.00	\$3.00