










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
<b>COMPRESSORS</b>					
<b>COM-CAQ</b>	 <b>CAPACITORS &amp; START DEVICES</b>				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$106.76	\$152.10	\$90.75	\$16.01
<b>COM-CHQ</b>					
<b>COM-CHQ</b>	 <b>HERMETIC COMPOSITE * MECH FAILURE</b>				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,630.04	\$1,998.09	\$1,385.54	\$244.51
<b>CONDENSATE</b>					
<b>COD-COP</b>	 <b>CONDENSATE PUMPS</b>				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$171.64	\$204.79	\$145.89	\$25.75
<b>CONTROLS</b>					
<b>CON-COU</b>	 <b>CONTACTORS * 2 POLE</b>				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$117.01	\$162.35	\$99.46	\$17.55
<b>GAS HEATING</b>					
<b>GAS-IGO</b>	 <b>IGNITORS</b>				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$159.83	\$217.92	\$135.86	\$23.98
<b>GAS-THR</b>					
<b>GAS-THR</b>	 <b>THERMOCOUPLES</b>				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$116.03	\$165.61	\$98.62	\$17.40
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$25.36	\$29.61	\$21.56	\$3.80
<b>MOTORS</b>					
<b>MOT-CFN</b>	 <b>COND FAN MOTORS * SLEEVE BEARINGS</b>				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$314.74	\$405.69	\$267.53	\$47.21
<b>MOT-MOD</b>					
<b>MOT-MOD</b>	 <b>DIRECT DRIVE MOTORS</b>				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$462.91	\$592.96	\$393.47	\$69.44
<b>REFRIGERANTS</b>					
<b>REF-RRR</b>	 <b>REFRIGERANTS</b>				
017660-0011	R22 PER LB (1st LB)	\$52.60	\$67.90	\$44.71	\$7.89
017661-0000	R22 PER LB (ADDL LBS)	\$22.00	\$22.00	\$18.70	\$3.30