










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
COMPRESSORS					
COM-CAQ	 CAPACITORS & START DEVICES				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$112.10	\$160.10	\$95.28	\$16.81
COM-CHQ					
COM-CHQ	 HERMETIC COMPOSITE * MECH FAILURE				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,673.34	\$2,063.04	\$1,422.34	\$251.00
CONDENSATE					
COD-COP	 CONDENSATE PUMPS				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$175.54	\$210.64	\$149.21	\$26.33
CONTROLS					
CON-COU	 CONTACTORS * 2 POLE				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$122.35	\$170.35	\$103.99	\$18.35
GAS HEATING					
GAS-IGO	 IGNITORS				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$166.67	\$228.17	\$141.67	\$25.00
GAS-THR	 THERMOCOUPLES				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$121.86	\$174.36	\$103.58	\$18.28
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$25.86	\$30.36	\$21.98	\$3.88
MOTORS					
MOT-CFN	 COND FAN MOTORS * SLEEVE BEARINGS				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$325.44	\$421.74	\$276.62	\$48.82
MOT-MOD	 DIRECT DRIVE MOTORS				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$478.21	\$615.91	\$406.48	\$71.73
REFRIGERANTS					
REF-RRR	 REFRIGERANTS				
017660-0011	R22 PER LB (1st LB)	\$56.40	\$72.60	\$47.94	\$8.46
017661-0000	R22 PER LB (ADDL LBS)	\$24.00	\$24.00	\$20.40	\$3.60