










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
<b>COMPRESSORS</b>					
<b>COM-CAQ</b>	 <b>CAPACITORS &amp; START DEVICES</b>				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$133.43	\$192.10	\$113.41	\$20.01
<b>COM-CHQ</b>					
<b>COM-CHQ</b>	 <b>HERMETIC COMPOSITE * MECH FAILURE</b>				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,846.54	\$2,322.84	\$1,569.56	\$276.98
<b>CONDENSATE</b>					
<b>COD-COP</b>	 <b>CONDENSATE PUMPS</b>				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$191.14	\$234.04	\$162.47	\$28.67
<b>CONTROLS</b>					
<b>CON-COU</b>	 <b>CONTACTORS * 2 POLE</b>				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$143.68	\$202.35	\$122.13	\$21.55
<b>GAS HEATING</b>					
<b>GAS-IGO</b>	 <b>IGNITORS</b>				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$194.00	\$269.17	\$164.90	\$29.10
<b>GAS-THR</b>					
<b>GAS-THR</b>	 <b>THERMOCOUPLES</b>				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$145.19	\$209.36	\$123.41	\$21.78
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$27.86	\$33.36	\$23.68	\$4.18
<b>MOTORS</b>					
<b>MOT-CFN</b>	 <b>COND FAN MOTORS * SLEEVE BEARINGS</b>				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$368.24	\$485.94	\$313.00	\$55.24
<b>MOT-MOD</b>					
<b>MOT-MOD</b>	 <b>DIRECT DRIVE MOTORS</b>				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$539.41	\$707.71	\$458.50	\$80.91
<b>REFRIGERANTS</b>					
<b>REF-RRR</b>	 <b>REFRIGERANTS</b>				
017660-0011	R22 PER LB (1st LB)	\$67.60	\$87.40	\$57.46	\$10.14
017661-0000	R22 PER LB (ADDL LBS)	\$28.00	\$28.00	\$23.80	\$4.20