










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
COMPRESSORS					
COM-CAQ	 CAPACITORS & START DEVICES				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$144.10	\$208.10	\$122.48	\$21.61
COM-CHQ					
COM-CHQ	 HERMETIC COMPOSITE * MECH FAILURE				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,933.14	\$2,452.74	\$1,643.17	\$289.97
CONDENSATE					
COD-COP	 CONDENSATE PUMPS				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$198.94	\$245.74	\$169.10	\$29.84
CONTROLS					
CON-COU	 CONTACTORS * 2 POLE				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$154.35	\$218.35	\$131.19	\$23.15
GAS HEATING					
GAS-IGO	 IGNITORS				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$207.67	\$289.67	\$176.52	\$31.15
GAS-THR	 THERMOCOUPLES				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$156.86	\$226.86	\$133.33	\$23.53
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$28.86	\$34.86	\$24.53	\$4.33
MOTORS					
MOT-CFN	 COND FAN MOTORS * SLEEVE BEARINGS				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$389.64	\$518.04	\$331.19	\$58.45
MOT-MOD	 DIRECT DRIVE MOTORS				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$570.01	\$753.61	\$484.51	\$85.50
REFRIGERANTS					
REF-RRR	 REFRIGERANTS				
017660-0011	R22 PER LB (1st LB)	\$71.20	\$92.80	\$60.52	\$10.68
017661-0000	R22 PER LB (ADDL LBS)	\$28.00	\$28.00	\$23.80	\$4.20