










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
COMPRESSORS					
COM-CAQ	 CAPACITORS & START DEVICES				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$80.10	\$112.10	\$68.08	\$12.01
COM-CHQ					
COM-CHQ	 HERMETIC COMPOSITE * MECH FAILURE				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,413.54	\$1,673.34	\$1,201.51	\$212.03
CONDENSATE					
COD-COP	 CONDENSATE PUMPS				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$152.14	\$175.54	\$129.32	\$22.82
CONTROLS					
CON-COU	 CONTACTORS * 2 POLE				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$90.35	\$122.35	\$76.79	\$13.55
GAS HEATING					
GAS-IGO	 IGNITORS				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$125.67	\$166.67	\$106.82	\$18.85
GAS-THR	 THERMOCOUPLES				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$86.86	\$121.86	\$73.83	\$13.03
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$22.86	\$25.86	\$19.43	\$3.43
MOTORS					
MOT-CFN	 COND FAN MOTORS * SLEEVE BEARINGS				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$261.24	\$325.44	\$222.05	\$39.19
MOT-MOD	 DIRECT DRIVE MOTORS				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$386.41	\$478.21	\$328.45	\$57.96
REFRIGERANTS					
REF-RRR	 REFRIGERANTS				
017660-0011	R22 PER LB (1st LB)	\$38.60	\$49.40	\$32.81	\$5.79
017661-0000	R22 PER LB (ADDL LBS)	\$17.00	\$17.00	\$14.45	\$2.55