










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
COMPRESSORS					
COM-CAQ	 CAPACITORS & START DEVICES				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$85.43	\$120.10	\$72.61	\$12.81
COM-CHQ					
COM-CHQ	 HERMETIC COMPOSITE * MECH FAILURE				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,456.84	\$1,738.29	\$1,238.32	\$218.53
CONDENSATE					
COD-COP	 CONDENSATE PUMPS				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$156.04	\$181.39	\$132.63	\$23.41
CONTROLS					
CON-COU	 CONTACTORS * 2 POLE				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$95.68	\$130.35	\$81.33	\$14.35
GAS HEATING					
GAS-IGO	 IGNITORS				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$132.50	\$176.92	\$112.63	\$19.88
GAS-THR	 THERMOCOUPLES				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$92.69	\$130.61	\$78.79	\$13.90
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$23.36	\$26.61	\$19.86	\$3.50
MOTORS					
MOT-CFN	 COND FAN MOTORS * SLEEVE BEARINGS				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$271.94	\$341.49	\$231.15	\$40.79
MOT-MOD	 DIRECT DRIVE MOTORS				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$401.71	\$501.16	\$341.45	\$60.26
REFRIGERANTS					
REF-RRR	 REFRIGERANTS				
017660-0011	R22 PER LB (1st LB)	\$41.40	\$53.10	\$35.19	\$6.21
017661-0000	R22 PER LB (ADDL LBS)	\$18.00	\$18.00	\$15.30	\$2.70