










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
COMPRESSORS					
COM-CAQ	 CAPACITORS & START DEVICES				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$96.10	\$136.10	\$81.68	\$14.41
COM-CHQ					
COM-CHQ	 HERMETIC COMPOSITE * MECH FAILURE				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,543.44	\$1,868.19	\$1,311.93	\$231.52
CONDENSATE					
COD-COP	 CONDENSATE PUMPS				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$163.84	\$193.09	\$139.26	\$24.58
CONTROLS					
CON-COU	 CONTACTORS * 2 POLE				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$106.35	\$146.35	\$90.39	\$15.95
GAS HEATING					
GAS-IGO	 IGNITORS				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$146.17	\$197.42	\$124.24	\$21.93
GAS-THR	 THERMOCOUPLES				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$104.36	\$148.11	\$88.71	\$15.65
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$24.36	\$28.11	\$20.71	\$3.65
MOTORS					
MOT-CFN	 COND FAN MOTORS * SLEEVE BEARINGS				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$293.34	\$373.59	\$249.34	\$44.00
MOT-MOD	 DIRECT DRIVE MOTORS				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$432.31	\$547.06	\$367.46	\$64.85
REFRIGERANTS					
REF-RRR	 REFRIGERANTS				
017660-0011	R22 PER LB (1st LB)	\$47.00	\$60.50	\$39.95	\$7.05
017661-0000	R22 PER LB (ADDL LBS)	\$20.00	\$20.00	\$17.00	\$3.00