










REPAIR #	DESCRIPTION	Repair Fee	After Hours	Service Agreement	Agreement Savings
COMPRESSORS					
COM-CAQ	 CAPACITORS & START DEVICES				
017826-0032	RUN CAPACITOR REPLACE 20 - 35 MFD X 440V	\$117.43	\$168.10	\$99.81	\$17.61
COM-CHQ					
COM-CHQ	 HERMETIC COMPOSITE * MECH FAILURE				
018591-0420	HERMETIC COMPRESSOR REPLACE 36,000 BTU 208/230v 1 PH	\$1,716.64	\$2,127.99	\$1,459.15	\$257.50
CONDENSATE					
COD-COP	 CONDENSATE PUMPS				
025232-0021	BECKETT CONDENSATE PUMP CB20-1VL 1/50hp, 115v, w/check valve & safety switch	\$179.44	\$216.49	\$152.52	\$26.92
CONTROLS					
CON-COU	 CONTACTORS * 2 POLE				
027192-0032	CUTLER-HAMMER CONTACTOR C25BNB230T	\$127.68	\$178.35	\$108.53	\$19.15
GAS HEATING					
GAS-IGO	 IGNITORS				
022173-0041	HOT SURFACE IGNITOR REPLACE, UNIVERSAL See Tech Notes at this Tab.	\$173.50	\$238.42	\$147.48	\$26.03
GAS-THR	 THERMOCOUPLES				
016941-0035	HW TCPL REPLACE Q340A1090, 36"	\$127.69	\$183.11	\$108.54	\$19.15
016615-0003	HW TCPL REPLACE Q340A1090, 36" w/BURNER REMOVED	\$26.36	\$31.11	\$22.41	\$3.95
MOTORS					
MOT-CFN	 COND FAN MOTORS * SLEEVE BEARINGS				
018200-0104	COND FAN MTR REPLACE 1/3HP 230V 1075 RPM	\$336.14	\$437.79	\$285.72	\$50.42
MOT-MOD	 DIRECT DRIVE MOTORS				
016825-0132	DIRECT DRIVE MTR REPLACE 3/4HP 115V 1075 RPM	\$493.51	\$638.86	\$419.48	\$74.03
REFRIGERANTS					
REF-RRR	 REFRIGERANTS				
017660-0011	R22 PER LB (1st LB)	\$60.20	\$77.30	\$51.17	\$9.03
017661-0000	R22 PER LB (ADDL LBS)	\$26.00	\$26.00	\$22.10	\$3.90